

VACUUM APPLICATIONS

WARNING

The negative pressure head in the instrument capillary added to the negative process pressure can be greater than -1 bar. This is not possible and the instrument will not function correctly, also the diaphragm can be damaged beyond repair.

